



**Figure 18-3** Garden hose placed briefly in wall cavity to test for obstruction of water flow to weeps.



**Figure 18-4** Water should drain immediately and freely from the weep hole immediately below the test location.

